



Figure 116. Metallic Particles on Second-Stage Diffuser Vanes